## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,924,770 B2 **DATED** : August 2, 2005

INVENTOR(S) : Carpenter et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 11,

Line 5, should read -- internal antenna when the second antenna is not in position on --.

Signed and Sealed this

Page 1 of 1

Twenty-seventh Day of December, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office